


Skaneateles Lake Water Service Illustration

Illustration is not to scale



WATER SAMPLE TEST RESULTS, 2024

SAMPLE LOCATION AND DATE	7/8	7/15	7/22	7/29	8/5	8/12	8/19	8/26	9/3	9/9	9/16	9/17	9/23	9/30	10/7	10/15			
1 Skaneateles Gatehouse-Intake 1	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND			
2 Skaneateles Gatehouse-Intake 2	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND			
3 Clear Well 1/2 at Gatehouse	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
4 Clear Well 3 at Gatehouse	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
5 Skaneateles UV Plant	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
6 Elbridge UV Plant	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
7 Westcott Incoming	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
8 Westcott Outgoing to Syracuse	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
9 Woodland Incoming	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
10 Woodland Outgoing to Syracuse	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
11 Skaneateles HS	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
12 Byrne Dairy	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
13 Elbridge-North	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
14 Jordan Town Hall	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			
15 Syracuse-Burnet & Thompson	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-			

Values in parts per billion (ppb)
 ND = Non Detect, equals less than the required method reporting limit of 0.3 µg/l
 "-" = Not Sampled



ongovhealth
Onondaga County
Health Department