


Skaneateles Lake Water Service Illustration

Illustration is not to scale



WATER SAMPLE TEST RESULTS, 2021

Values in parts per billion (ppb). Weekly testing of Skaneateles Gatehouse Intakes 1 and 2 began 7-7-21 with ND* results for all samples.

SAMPLE LOCATION AND DATE	8-2	8-9	8-16	8-23	8-30	9-7	9-13	9-17	9-20	9-23	9-27	10-4	10-6	10-9	10-11	10-13	10-18	10-25
1 Skaneateles Gatehouse-Intake 1	ND	ND	ND	ND	ND	ND	.364	.39	.313	.471	ND	.359	ND	ND	ND	ND	ND	ND
2 Skaneateles Gatehouse-Intake 2	ND	ND	ND	ND	ND	ND	.456	.79	.606	.485	ND	ND	.306	ND	ND	ND	ND	ND
3 Clear Well 1/2 at Gatehouse	-	-	-	-	-	-	-	ND	-	ND	ND	-	-	ND	ND	-	-	-
4 Clear Well 3 at Gatehouse	-	-	-	-	-	-	-	ND	-	ND	ND	-	-	ND	ND	-	-	-
5 Skaneateles UV Plant	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
6 Elbridge UV Plant	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
7 Westcott Incoming	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
8 Westcott Outgoing to Syracuse	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
9 Woodland Incoming	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
10 Woodland Outgoing to Syracuse	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
11 Skaneateles HS	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
12 Byrne Dairy	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
13 Elbridge-North	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
14 Jordan Town Hall	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-
15 Syracuse-Burnet & Thompson	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-

*ND = Non Detect, equals less than the required method reporting limit of 0.3 µg/l
 "-" = Not Sampled