


Skaneateles Lake Water Service Illustration

Illustration is not to scale



WATER SAMPLE TEST RESULTS, 2019

| | 7-1 | 7-8 | 7-15 | 7-29 | 8-5 | 8-12 | 8-19 | 8-26 | 9-3 | 9-5 | 9-6 | 9-9 | 9-16 | 9-23 | 9-30 | 10-15 | | | |
|---|-----|-----|------|------|-----|------|------|------|-----|-----|-----|-----|------|------|------|-------|--|--|--|
| 1 Skaneateles Gatehouse-Intake 1 | ND | ND | ND | ND | ND | ND | ND | ND | ND | ND | ND | ND | ND | ND | ND | | | | |
| 2 Skaneateles Gatehouse-Intake 2 | ND | ND | ND | ND | ND | ND | ND | ND | ND | ND | ND | ND | ND | ND | ND | | | | |
| 3 Clear Well 1/2 at Gatehouse | - | - | - | - | - | - | - | - | - | - | ND | - | - | - | - | | | | |
| 4 Clear Well 3 at Gatehouse | - | - | - | - | - | - | - | - | - | - | ND | - | - | - | - | | | | |
| 5 Skaneateles UV Plant | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | | | | |
| 6 Elbridge UV Plant | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | | | | |
| 7 Westcott Incoming | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | | | | |
| 8 Westcott Outgoing to Syracuse | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | | | | |
| 9 Woodland Incoming | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | | | | |
| 10 Woodland Outgoing to Syracuse | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | | | | |
| 11 Skaneateles HS | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | | | | |
| 12 Byrne Dairy | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | | | | |
| 13 Elbridge-North | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | | | | |
| 14 Jordan Town Hall | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | | | | |
| 15 Syracuse-Burnet & Thompson | - | - | - | - | - | - | - | - | - | - | - | - | - | - | - | | | | |

Values in parts per billion (ppb)
 ND = Non Detect, equals less than the required method reporting limit of 0.3 µg/l
 "-" = Not Sampled